

**SPRINKLER CHECK LOG**

**NLT Quarterly Inspection Schedule**

DATE	BY	ITEM / STATUS
6/3/2015	Cliff	Repair Broken Spray Head Pipe - East Beds
6/10/2015	Cliff	Replace Rain Sensor - Required by FS 373.62
6/18/2015	Cliff	Replace Controller Backup Battery / Rewire Common Lead
7/2/2015	Cliff	Zones Operating OK / No Broken Spray or Rotor Heads
7/10/2015	Cliff	Add Power Cord Clamp / Caulk Wire Openings
7/12/2015	Cliff	Zones Operating OK / No Broken Spray or Rotor Heads
7/19/2015	Cliff	Rain Sensor Operating OK / Controller Time OK
8/2/2015	Cliff	Time wrong. Reset. Rain Sensor working. Email to Hunter and NLT re time problem.
8/5/2015	Cliff	Run Sprinklers for BKTurf monthly application. Time OK. Zone 1 OK.
8/11/2015	Cliff	Controller Reset and Reprogram - last step before requesting replacement.
8/17/2015	Cliff	NLT offered to replace Controller - deferred pending results of reset.
8/28/2015	Cliff	Zones Operating OK / No Broken Spray or Rotor Heads. Timer OK
9/3/2015	Cliff	Run Sprinklers for BKTurf monthly application. Time OK. Zones all OK.
9/10/2015	NLT	Quarterly Inspection - 5 rotors leaking / to be replaced
9/15/2015	Cliff	Wednesday early AM sprinkler operation completed as scheduled
9/20/2015	Cliff	Time checked - OK. 5 Rotors to be replaced by NLT - see mapping
9/22/2015	Cliff	NLT repairs completed. Timer ok. Heads rings ok zones 1 3.
11/4/2015	Cliff	Overnite watering as scheduled
11/4/2015	Cliff	Run Sprinklers for BKTurf monthly application @ 6:15PM
11/27/2015	Cliff	Timer Checked and reset for EST (Lights Also). Zones Checked. 1 Repair Completed
Dec	NLT	Irrigation System Check - 2 heads replaced. Per Jasmine
1/1/2016	Cliff	Timer OK. No broken heads / some need pattern adjusted.
2/11/2016	Cliff	Timer OK. No broken heads. 1 spray not retracting West side of entrance island
3/14/2016	Cliff	Timers (irrigation, lights) reset for DST
4/6/2016	Cliff	Irrigation System Check - 1 head adjusted zone 1; 1 head cleared zone 5
May-June	Cliff	Irrigation System Check - 1 sticking head "cleared" zone 5
7/22/2016	Cliff	Controller Timer Lost Settings- Reprogrammed
8/22/2016	Cliff	Checked Timer - OK - Reset Rain Sensor to 1/4"
8/25/2016	NLT	Repaired broken rotor and spray heads
9/7/2016	Cliff	Rain Sensor set to 1/4"
9/7/2016	Cliff	Checked Timer - OK. Checked system - found one broken spray head - repaired 9/8
9/22/2016	Cliff	Checked Timer and all sprinkler rotors/spray heads - all OK
Oct	Cliff	Checked Timer and all sprinkler rotors/spray heads - all OK
11/5/2016	Cliff	Reset time for end of Daylight Saving Time
Nov	NLT	NLT repairs completed - 2 rotors / cap 2 bubblers.
11/25/2016	Cliff	Reset Timer and all sprinkler rotors/spray heads - all OK
2/12/2017	Cliff	Timer OK. All sprinkler/rotor heads running OK
2/25/2017	Cliff	18 Rotors Center Island - Grass over sprinkler head rings cut/removed
April	Cliff	Checked Timer and all sprinkler rotors/spray heads - all OK
May	Cliff	Repaired one broken spray head
May	Cliff	Timer running off cycle - reset time
5/25/2017	Cliff & Ron	Found 1 broken Rotor East Sidewalk and 1 damaged Spray Head Entrance Island.
5/30/2017	NLT	Inspection; Repair Rotor; 12" Spray Head requires additional repair. Recommended split of last rotor South side of center grass island into 2 rotors.
5/30/2017	Central Pro	Quote for recommended Hunter Controller 52C-XC-600 - \$68+tax=\$72.76
7/25/2017	Cliff	Checked Timer and all sprinkler rotors/spray heads - all OK except 1 known issue
9/14/2017	Cliff	Timer checked after 3 day power outage - all ok
9/21/2017	Cliff	Zones checked - all spray/rotor heads working ok
9/23/2017	Cliff	Checked that system watered Sat AM per settings - all OK